2021 Pumping Plant Summary Report Overall Unit and Item Ratings

City of Sacramento

Magpie Creek Pumping Plant

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	Α
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	M
	Cranes	Α
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	Α
	Sluice / Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	N
	Security Fencing	Α
	Intake and Discharge Pipes	Α

2021 Pumping Plant Summary Report Overall Unit and Item Ratings

Reclamation District No. 2063 Crows Landing

Lateral No. 6 Pumping Plant

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	Α
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	N
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	N
	Sluice / Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	N
	Security Fencing	N
	Intake and Discharge Pipes	Α

2021 Pumping Plant Summary Report Overall Unit and Item Ratings

DWR Sutter Maintenance Yard

Middle Creek Pumping Plant

Overall Unit Rating	Rated Item	Item Rating
Α	Operating Log	Α
	Operation & Maintenance Manual	Α
	Plant Building	M
	Communications	Α
	Safety	Α
	Cranes	N
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	N
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	N
	Sluice / Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	N
	Closure Structures	N
	Security Fencing	Α
	Intake and Discharge Pipes	A

2021 Pumping Plant Summary Report Overall Unit and Item Ratings

DWR Sutter Maintenance Yard (cont.)

Sutter Bypass Pumping Plant No. 1

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	Α
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	N
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	N
	Sluice / Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	N
	Security Fencing	Α
	Intake and Discharge Pipes	Α

2021 Pumping Plant Summary Report Overall Unit and Item Ratings

DWR Sutter Maintenance Yard (cont.)

Sutter Bypass Pumping Plant No. 2

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	А
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	N
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	N
	Sluice / Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	N
	Security Fencing	Α
	Intake and Discharge Pipes	Α

2021 Pumping Plant Summary Report Overall Unit and Item Ratings

DWR Sutter Maintenance Yard (cont.)

Sutter Bypass Pumping Plant No. 3

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	А
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	N
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	N
	Sluice / Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	N
	Security Fencing	Α
	Intake and Discharge Pipes	Α

2021 Pumping Plant Summary Report Overall Unit and Item Ratings

Turlock Irrigation District Gomes Lake

Gomes Lake Pumping Plant

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	Α
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	N
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	N
	Sluice / Slide Gates	Α
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	N
	Security Fencing	Α
	Intake and Discharge Pipes	Α

2021 Pumping Plant Summary Report Overall Unit and Item Ratings

Sacramento County

American River Pumping Plant No. 1 Howe Avenue Storm Drain D - 05

Overall Unit Rating	Rated Item	Item Rating
Α	Operating Log	Α
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	Α
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	M
	Sluice / Slide Gates	Α
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	N
	Security Fencing	Α
	Intake and Discharge Pipes	Α

2021 Pumping Plant Summary Report Overall Unit and Item Ratings

Sacramento County (cont.)

American River Pumping Plant No. 2 Willhaggin Storm Drain D - 43

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	Α
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	Α
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	N
	Sluice / Slide Gates	Α
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	N
	Security Fencing	Α
	Intake and Discharge Pipes	Α

2021 Pumping Plant Summary Report Overall Unit and Item Ratings

San Joaquin County Flood Control and Water Conservation District

Mormon Slough Pumping Plant No. 1

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	Α
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	M
	Cranes	N
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	N
	Sluice / Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	N
	Security Fencing	M
	Intake and Discharge Pipes	Α

2021 Pumping Plant Summary Report Overall Unit and Item Ratings

San Joaquin County Flood Control and Water Conservation District (cont.)

Mormon Slough Pumping Plant No. 2

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	Α
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	N
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	N
	Sluice / Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	N
	Security Fencing	Α
	Intake and Discharge Pipes	Α

2021 Pumping Plant Summary Report Overall Unit and Item Ratings

San Joaquin County Flood Control and Water Conservation District (cont.)

Mormon Slough Pumping Plant No. 3

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	Α
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	N
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	А
	Trash Rakes	N
	Sluice / Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	N
	Security Fencing	Α
	Intake and Discharge Pipes	Α

2021 Pumping Plant Summary Report Overall Unit and Item Ratings

Reclamation District No. 2096 Wetherbee Lake

Wetherbee Lake Pumping Plant & Navigation Gate

Overall Unit Rating	Rated Item	Item Rating
M	Operating Log	Α
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	A
	Safety	M
	Cranes	N
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	M
	Trash Rakes	N
	Sluice / Slide Gates	N
	Electric Gate Operators	Α
	Manual Gate Operators	U
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	Α
	Security Fencing	Α
	Intake and Discharge Pipes	Α